


5.6 Hose Assembly Orientation For Offset Elbow Fittings

SO# _____

Figure 5.6.1. Offset Angles

WO# _____



How to Measure

The offset angle is determined by the number of degrees measured in a counter-clockwise direction between the fitting nearest the viewer and the farthest end fitting.

Offset Angle Tolerances

± 3 degrees on lengths up to 24 inches (609.6 mm).

± 5 degrees on lengths 24 inches (609.6 mm) and longer

HATEC INTERNATIONAL, INC.

122 JOHN STOCKBAUER DR.
VICTORIA, TX 77901
TEL: 361-580-1931
FAX: 361-580-1941

7561 TYLER BLVD., STE. 1
MENTOR, OH 44060
TEL: 440-946-4673
FAX: 440-946-3393
TOLL FREE: 866-963-8742

2222 W. VALLEY HWY N STE. 170
AUBURN, WA 98001
TEL: 253-886-5606
FAX: 253-886-5609
TOLL FREE: 877-886-5606

12005 JACK BENNY DR. STE. 103
RANCHO CUCAMONGA, CA 91739
TEL: 909-948-7060
FAX: 909-948-7025
TOLL FREE: 866-863-8742

5515 N. HWY 35
ALVIN, TX 77511
TEL: 281-585-6151
FAX: 281-585-6153